Galaxy Cloud
Migration

Hardware

Existing Galaxy (635 Series) panels could simply require a flash update. Legacy Galaxy panels need to be replaced. INon-Galaxy hardware will need to be removed, and the IP addresses should be migrated to new Galaxy panels. DHCP is optional but a static IP is recommended.

Peripherals

Readers, Credentials, Locks, Door Contacts, REX, Motion Sensors typically can be reused unless the reader and credential are proprietary to the previous manufacturer. Galaxy works with most reader and credential manufacturers. The reader and credential can be sent to Galaxy for evaluation if there are any doubts.

Database

With existing Galaxy databases, a backup should be done and sent to Galaxy for evaluation. Typically, the database can be migrated into the cloud without further action. If it is not a Galaxy database, contact the previous manufacturer's support to get an export of the cardholder and card information or a backup of the database. The data can then be imported into Galaxy's cloud.